

Sedgman Limited [ASX: SDM]

ABN 86 088 471 667

Head Office

Level 2, 2 Gardner Close
Milton QLD 4064
AUSTRALIA
Ph: +61 7 3514 1000
Fax: +61 7 3514 1999

Postal Address

PO Box 1801
Milton QLD 4064
AUSTRALIA
Email: mail@sedgman.com
Web: www.sedgman.com



Cullen Valley Mine

Annual Environmental Management Report 2015



LC/lc

Revision: 1.0

Revision Status

Revision Number	Author	Description	Date	Approved By
Draft	L. Clough	Draft for review	20-Jan-2016	A. O'Brien
1.0	L. Clough	Final for submission	22-Jan-2016	A. O'Brien

Distribution

Company Name	Contact Name	Revision	Date
Castlereagh Coal	Brett Moore	1.0	22-Jan-2016
Invincible Colliery	John Duffy	1.0	22-Jan-2016
Department of Trade & Investment	Chris Hammersley	1.0	22-Jan-2016

Copyright Notice

Sedgman © 2016

This Document is copyright. Other than for the purposes and subject to the conditions prescribed under the Copyright Act 1968 (Commonwealth), no part of it may in any form or by any means (electronic, mechanical, micro-copying, photocopying, recording or otherwise) be reproduced, stored in a retrieval system or transmitted without prior written permission.

Table of Contents

Title Block	1
1 Introduction	2
1.1 Consents, Leases and Licences	2
1.2 Mine Contacts	2
1.3 Actions Required at Previous AEMR Review	3
2 Operations during the Reporting Period	4
2.1 Exploration	4
2.2 Land Preparation	4
2.3 Construction	4
2.4 Mining	4
2.5 Coal Processing	4
2.6 Waste Management	4
2.7 Product Stockpiles	5
2.8 Water Management	5
2.9 Hazardous Material Management	5
2.10 Other Infrastructure Management	6
3 Environmental Management and Performance	7
3.1 Environmental Risk Assessment	7
3.2 Environmental Risk Management	7
3.3 Reporting Requirements	12
3.4 Meteorological Monitoring	12
3.4.1 Rainfall	12
3.4.2 Temperature	12
3.4.3 Wind Speed and Direction	12
3.4.4 Humidity	12
3.5 Air Quality	13
3.5.1 Environmental Management	13
3.5.2 Environmental Performance	13
3.5.3 Reportable Incidents	14
3.5.4 Further Improvements	15
3.6 Erosion and Sedimentation	15
3.6.1 Environmental Management	15
3.6.2 Environmental Performance	15
3.6.3 Reportable Incidents	16
3.6.4 Further Improvements	16
3.7 Surface Water	17
3.7.1 Environmental Management	17
3.7.2 Environmental Performance	17
3.7.3 Reportable Incidents	17
3.7.4 Further Improvements	18
3.8 Ground Water	18
3.8.1 Environmental Management	18
3.8.2 Environmental Performance	18
3.8.3 Reportable Incidents	20
3.8.4 Further Improvements	20
3.9 Contaminated Land	20
3.9.1 Environmental Management	20
3.9.2 Environmental Performance	21
3.9.3 Reportable Incidents	21
3.9.4 Further Improvements	21
3.10 Threatened Flora and Fauna	21

3.10.1	Environmental Management	21
3.10.2	Environmental Performance	21
3.10.3	Reportable Incidents	21
3.10.4	Further Improvements	21
3.11	Weeds	22
3.11.1	Environmental Management	22
3.11.2	Environmental Performance	22
3.11.3	Reportable Incidents	22
3.11.4	Further Improvements	22
3.12	Blasting	23
3.12.1	Environmental Management	23
3.12.2	Environmental Performance	23
3.12.3	Reportable Incidents	23
3.12.4	Further Improvements	23
3.13	Operational Noise	23
3.13.1	Environmental Management	23
3.13.2	Environmental Performance	23
3.13.3	Reportable Incidents	25
3.13.4	Further Improvements	25
3.14	Visual, Stray Light	25
3.14.1	Environmental Management	25
3.14.2	Environmental Performance	25
3.14.3	Reportable Incidents	25
3.14.4	Further Improvements	26
3.15	Aboriginal Heritage	26
3.15.1	Environmental Management	26
3.15.2	Environmental Performance	26
3.15.3	Reportable Incidents	26
3.15.4	Further Improvements	26
3.16	European Heritage	26
3.16.1	Environmental Management	26
3.16.2	Environmental Performance	27
3.16.3	Reportable Incidents	27
3.16.4	Further Improvements	27
3.17	Spontaneous Combustion and Subsurface Heating	27
3.17.1	Environmental Management	27
3.17.2	Environmental Performance	27
3.17.3	Reportable Incidents	28
3.17.4	Further Improvements	28
3.18	Bushfire	28
3.18.1	Environmental Management	28
3.18.2	Environmental Performance	29
3.18.3	Reportable Incidents	29
3.18.4	Further Improvements	29
3.19	Mine Subsidence	29
3.19.1	Environmental Management	29
3.19.2	Environmental Performance	29
3.19.3	Reportable Incidents	29
3.19.4	Further Improvements	29
3.20	Hydrocarbon Contamination	29
3.20.1	Environmental Management	29
3.20.2	Environmental Performance	30
3.20.3	Reportable Incidents	30
3.20.4	Further Improvements	30
3.21	Methane Drainage/Ventilation	30
3.21.1	Environmental Management	30
3.21.2	Environmental Performance	30
3.21.3	Reportable Incidents	30
3.21.4	Further Improvements	30

3.22	Public Safety	30
3.22.1	Environmental Management	30
3.22.2	Environmental Performance	31
3.22.3	Reportable Incidents	31
3.22.4	Further Improvements	31
3.23	Other Issues and Risks	31
4	Community Relations	32
4.1	Environmental Complaints	32
4.2	Community Liaison	32
4.2.1	Stakeholder Engagement	32
4.2.2	Consultation Completed in the Reporting Period	33
4.2.3	Proposed Future Consultation	33
5	Rehabilitation	34
5.1	Buildings	34
5.2	Other Infrastructure	34
5.3	Rehabilitation of Disturbed Land	34
5.3.1	Rehabilitation Goals and Objectives	34
5.3.2	Success of Rehabilitation Areas	34
5.3.3	Rehabilitation Works Undertaken during the Reporting Period	35
5.4	Rehabilitation Trials and Research	35
5.5	Further Development of the Final Rehabilitation Plan	36
6	Activities Proposed in the Next AEMR Period	37

Appendices

Appendix A

Site Plans

Appendix B

Wind Roses

List of Tables


Table 1: Consents, Leases and Licences	2
Table 2: Mine Contacts.....	2
Table 3: Production and Waste Schedule	6
Table 4: Stored Water	6
Table 5: Risk Assessment.....	8
Table 6: Cullen Valley Mine weather station summary	12
Table 7: Air quality impact assessment criteria	13
Table 8: Deposited dust monitoring results	14
Table 9: Particulate matter (PM ₁₀) and Total suspended particulates (TSP) results	14
Table 10: Water quality concentration limits.....	16
Table 11: Water quality monitoring results within site dams 11 December 2015	16
Table 12: Water quality monitoring results at downstream creeks (BSW01 and BSW02) and the Hillcroft Property (BSW03)	17
Table 13: 2015 groundwater monitoring results	19
Table 14: Blasting impact assessment criteria	23
Table 15: Noise impact assessment criteria DA 200-5-2003	23
Table 16: Noise impact assessment criteria EPL 10341	24
Table 17: Quarterly attended noise monitoring results	24
Table 18: Details of complaints received during 2015	32
Table 19: Stakeholder Engagement.....	32

Table 20: Details of meetings	33
Table 21: Rehabilitation Summary	37
Table 22: Maintenance Activities on Rehabilitated Land.....	37

List of Figures

Figure 1: Standing water levels in groundwater bores	20
Figure 2: Locality	3
Figure 3: Ownership	3
Figure 4: Mining Activities.....	3
Figure 5: Environmental Monitoring.....	3
Figure 6: Subsurface Heating Area Monitoring	3
Figure 7: Rehabilitation Activities	3

Title Block

Name of Mine		Cullen Valley Mine	
Titles/Mining Leases:		ML1455, ML1488, ML1556, ML1557,	
MOP Commencement Date:		14 February 2013	MOP Completion Date: 31 March 2016
AEMR Commencement Date:		1 January 2015	AEMR Completion Date: 31 December 2015
Name of Leaseholder:		Shoalhaven Coal Pty Ltd	
Name of Mine Operator:		Sedgman Limited	
Reporting Officer:		William (John) Duffy	
Title:		Mining Engineering Manager	
Signature:			
Date:		22 January 2016	

1 Introduction

This Annual Environmental Management Report (AEMR) has been prepared for the Cullen Valley Mine in compliance with Schedule 6, Condition 5 of the Development Consent 200-5-2003 and in accordance with the Department of Trade and Investment, Division of Resources and Energy (DRE) *Guidelines to the Mining, Rehabilitation and Environmental Management Process*.

Castlereagh Coal owns and manages the Cullen Valley Mine, which is located approximately 125km northwest of Sydney and north-west of the township of Cullen Bullen. The site locality is shown on **Figure 2, Appendix A**. Mining operations were suspended in 2013 and the mine is currently managed under a care and maintenance arrangement pending an application for recommencement of mining operations.

1.1 Consents, Leases and Licences

The current consents, leases and licences as well as the date of grant and expiry date are provided in Table 1. Details of the current Mining Operations Plan (MOP) and any amendments since the previous Annual Environmental Management Report (AEMR) are also provided.

Table 1: Consents, Leases and Licences

Document	Date Granted	Expiry Date
Development Approval DA 200-5-2003	19 August 2004	19 August 2025
EPL No 10341	10 December (Anniversary date)	Renewed annually
Mining Lease 1455	19 August 1999	18 August 2020
Mining Lease 1488	21 June 2001	20 June 2022
Mining Lease 1556	20 September 2004	19 September 2025
Mining Lease 1557	20 September 2004	19 September 2025
Exploration Licence 5712	10 April 2000	9 April 2014 (renewal application submitted)
Exploration Licence 6007	8 October 2002	7 October 2014 (renewal application submitted)
Authorisation 324	25 August 1983	9 April 2016
Authorisation 420	12 January 1990	9 April 2016
Water Access Licence 27898	16 January 2012	5 July 2015
Current Cullen Valley Mine C&M MOP	14 February 2013	31 March 2016
MOP Amendments since the previous AEMR	An updated C&M MOP has been prepared for Cullen Valley Mine since the previous AEMR and was submitted to DRE for review on 17 December 2015. This updated C&M MOP is expected to commence in April 2016.	

The ownership of land within and adjacent to the mine is shown on **Figure 3, Appendix A**.

1.2 Mine Contacts

The contact details for the current mine manager and environmental manager are provided in Table 2.

Table 2: Mine Contacts

Role	Name	Contact details
Mining Engineering Manager	William (John) Duffy	Invincible Colliery, Castlereagh Highway Cullen Bullen, NSW 2790 (02) 6359 0600 John.Duffy@sedgman.com

Role	Name	Contact details
Environmental Manager	Andrew O'Brien	Sedgman, Level 2, 2 Gardner Close Milton Qld 4064 (07) 3124 4501 Andrew.O'Brien@sedgman.com

1.3 Actions Required at Previous AEMR Review

The AEMR for the period 1 January 2014 to 31 December 2014 was reviewed and accepted by the Division of Resources and Energy (DRE) on 23 October 2015. There were no actions required as a result of the DRE review.

2 Operations during the Reporting Period

2.1 Exploration

As the site has been in care and maintenance since 2013, there were no exploration activities undertaken during the 2015 reporting period.

2.2 Land Preparation

As the site has been in care and maintenance since 2013, no land clearing was undertaken for mining activities during the 2015 reporting period.

2.3 Construction

As the site has been in care and maintenance since 2013, there were no construction activities undertaken during the 2015 reporting period.

2.4 Mining

As the site has been in care and maintenance since 2013, there were no mining activities undertaken during the 2015 reporting period.

Most mobile plant and equipment has been removed from the site. Any equipment remaining on site is periodically run, where possible, with pre-start inspections conducted at each instance. Small excavators and dozers are used periodically for short periods for specific tasks such as erosion controls and rehabilitation maintenance.

2.5 Coal Processing

As the site has been in care and maintenance since 2013, no coal processing activities occurred at Cullen Valley Mine during the 2015 reporting period.

2.6 Waste Management

As no mining activities were undertaken during the 2015 reporting period, minimal quantities of waste materials were required to be stored on site.

All sewage from the workshop areas is directed to septic systems which are pumped out by a licensed waste collection and disposal contractor on an as-needs basis.

Any maintenance works required on machinery and equipment is undertaken within existing bunded areas at the Cullen Valley Mine. Waste oils and grease from these bunded areas including the workshop, is pumped or gravity flows to an oil-water separator and is cleaned on an as needs basis.

Under emergency circumstances, i.e. breakdowns in the pit area, oils and grease is pumped from the equipment to a tank on the service truck using an evacuation pump and is subsequently transferred to the bulk waste oil storage tank at the maintenance workshop. All parts, packaging etc. are collected and transferred to the maintenance workshop for disposal or recycling.

Waste oils and grease stored at the maintenance workshop are collected by a licensed waste recycling contractor on an as needs basis. There were no mining activities undertaken during

the 2015 reporting period and as such only minimal oil and greases will be required to be stored on site.

All paper and general wastes from workshop areas is disposed of in garbage bins located adjacent to the workshop areas. The bins are regularly collected and the contents placed in large waste skip bins positioned adjacent to the heavy vehicle maintenance building to await removal by a licensed industrial waste collector. Industrial waste collection is undertaken as required.

2.7 Product Stockpiles

As there were no mining activities conducted, there was no coal stockpiled during the current reporting period.

2.8 Water Management

The water management system at Cullen Valley Mine has been designed, as far as possible, as a closed loop system. All water that enters the site via rainfall or through the water table is diverted to a series of settlement dams within the site.

There are four dams currently on site, two of which are licensed discharge points for the site. These are LD001 (Dam 1) and LD004 (Dam 4) as shown in **Figure 4, Appendix A**. Two other settlement dams (Dam 2 and Dam 3) are used to store water during heavy rainfall events from predominately hardstand areas and from batter slopes of the noise/visual bund. The dams are generally kept at low, approximately 1/3 of capacity, levels unless periods of extended dry conditions occur or are forecast.

The primary source of water for Cullen Valley Mine is from the abandoned and flooded Tyldesley Mine underground workings via the Tilley's Bore (GW01). The water is pumped from the workings to two 500,000L tanks. Distribution around the site is by gravity fed water mains.

Secondary sources of water come from the mine's pollution control dams. Any excess water captured in the open void (Pit 106) will be pumped to Dam 4. Water from Dam 4 can be transferred to Dam 1 to be used for dust suppression and/or pumped into the underground workings.

All rehabilitation areas are designed with large contour drains which capture runoff during rain events. Due to the location of a large section of the rehabilitation over the old underground workings of the abandoned Tyldesley Colliery, water that percolates through the soil will ultimately flow into the underground workings for storage. The water level of the underground workings is monitored and recorded on a regular basis.

In the event that heavy vehicles are required for planned activities or maintenance works and the haul road is used, a water cart will be made available to ensure air quality impacts are minimised. The water cart will draw water from designated water fill points as per the water management system. The potable water supply will continue to be sourced from an existing connection to the Fish River Water Supply pipeline.

2.9 Hazardous Material Management

Hazardous material storage tanks containing oils, grease and degreasers have been emptied, isolated and secured. Any additional storage tanks have been removed from the site. Storage tanks remaining onsite are kept emptied during the care and maintenance period.

Any bunds containing storage tanks or drums have been cleaned and are checked during regular statutory inspections. The above ground self banded diesel tanks (Transtank) is not currently operational during the care and maintenance period. Up to 35,000L of diesel may be stored in the facility if diesel is required for environmental works on site.

Two EPA registered radionuclide fixed radiation gauges (No. RR20215 and No. RR21832) have been decommissioned and are stored onsite. Regular inspections are carried out on the devices and the storage container.

A register of hazardous materials is maintained on site. In addition, any contractor is required to maintain a register of hazardous materials utilised by its operations and service personnel whilst activities are being undertaken at Cullen Valley Mine.

2.10 Other Infrastructure Management

No production occurred during the reporting period. A summary of the production figures and mining activity for 2015 and the forecast production expectations for 2016 are summarised in Table 3.

Table 3: Production and Waste Schedule

	Cumulative Production (m ³)		
	<i>Start of Reporting Period</i>	<i>End of reporting period</i>	<i>End of next reporting period (estimated)</i>
Topsoil stripped	0	0	0
Topsoil used/spread	0	0	0
Waste rock	0	0	0
ROM coal	0	0	0
Processing waste	0	0	0
Product coal	0	0	0

The volumes of water stored on site during the 2015 reporting period are shown in Table 4.

Table 4: Stored Water

	Volumes Held (ML)		
	<i>Start of Reporting Period</i>	<i>End of reporting period</i>	<i>Storage Capacity</i>
Dam 1 – Dirty water	2.5	3.0	7.0
Dam 2 – Dirty water	10.0	8.0	30.0
Dam 3 – Dirty water	3.0	1.0	5.0
Dam 4 – Dirty water	15.0	10.0	38.0
LDP001 - Controlled discharge water	0.0	0.0	7.0
LDP004 - Controlled discharge water	0.0	0.0	38.0
Oil Water Separator - Contaminated water	0.0	0.0	0.01

3 Environmental Management and Performance

3.1 Environmental Risk Assessment

A formal risk assessment was undertaken by Sedgman Limited for the Cullen Valley Mine on 27 and 28 May 2015. A site tour was undertaken to ensure all areas of the Cullen Valley Mine and adjacent lands held within mining leases were considered in the scope of the risk assessment. The risk assessment was conducted in accordance with the Sedgman Ltd HSEQ Risk Management Procedure (HSE-PC-100000).

Risks identified during the assessment and the associated risk ratings are detailed in Table 5. Management controls are required for all items which have been identified as either high or medium risk. It is expected that current controls listed in Table 5 are sufficient to manage risks.

3.2 Environmental Risk Management

To ensure the implementation and effectiveness of control strategies for identified environmental risks, a number of management plans have been developed in consultation with regulators and other relevant stakeholders. Approved management plans at Cullen Valley Mine include the:

- Flora and Fauna Management Plan;
- Species Management Plan (Clandulla Geebung);
- Environmental Management Plan;
- Environmental Monitoring Program;
- Blast Management Plan;
- Fire Management Plan;
- PoW MOP Variation;
- Particulate Matter Pollution Reduction Program; and
- Pollution Incident Response Management Plan.

The Cullen Valley Mine is managed in accordance with approved Management Plans as required. Any variations required to the above Management Plans are undertaken in consultation with the Department of Industry – Division of Resources and Energy (DRE) and other relevant stakeholders.

Table 5: Risk Assessment

Risk Description	Current Controls	Consequence	Likelihood	Risk Rating
Strata Failure	Annual geological survey completed by competent expert Daily inspections or prior to entry from mining engineering manager Site in care and maintenance, limited persons onsite Visitors escorted by authorised persons	Major	Unlikely	High
Statutory non-compliance (electrical)	Electrical Engineering Manager appointed (caretaker mode) Electrical statutory checks in current Care and Maintenance MOP	Minor	Unlikely	Low
Statutory non-compliance (mechanical)	Mechanical Engineering Manager appointed (caretaker mode) Mechanical statutory checks in current Care and Maintenance MOP	Minor	Unlikely	Low
Unauthorised access to site	Locked gate to restrict access on all public accesses Highwall bunding along highwalls Security signs Locked buildings and equipment	Low	Unlikely	Low
Contractor Management	Inducted, trained and authorised personnel OTJ risk assessment, SWMS in place MDG15 inspections on equipment Familiar with work area Supervision by authorised persons	Minor	Unlikely	Low
Dust	Watercarts available when truck movements onsite Environmental monitoring as per Environmental Approval Licence Restricted access to pit	Low	Unlikely	Low
Water discharge offsite	Licensed discharge points Environmental dams Environmental monitoring as per Environmental Approval Licence Inspection after rainfall events Pit pumps in place Regular inspections Natural discharge points through Marangaroo sandstone Environmental Management Plan in place	Minor	Unlikely	Low
General waste/sewerage	Designated collection for waste - SITA Licensed sewerage collection from council on as needs basis - manual inspection Oil separators	Low	Unlikely	Low
Fuel/Oil Spills	Contained onsite Self-bunded fuel tanks (1 x 75000L not in use) Spill kits Servicing done in pit - decanted into containers and then disposed of through separator Light vehicles serviced offsite Fuel spills pipeline flows down to separator Approved disposal Current SHMS	Low	Unlikely	Low
Theft of equipment - fixed and mobile plant	Locked gate to restrict access on all public accesses Security signs Locked buildings and equipment	Low	Unlikely	Low

Damage to equipment - fixed and mobile plant	Equipment in care and maintenance Restricted access to site Power can be isolated at CHPP Regular statutory inspections of equipment	Minor	Unlikely	Low
Unauthorised use of equipment - fixed and mobile plant	Current SHMS - contractor management, training and authorisations and inductions	Minor	Unlikely	Low
Damage to infrastructure	Visual inspections by Mechanical Engineering Manager Structural integrity audits in the past Traffic management plans and signage	Minor	Unlikely	Low
Noise	Environmental monitoring as per Environmental Approval Licence Restricted access to pit Quarterly noise monitoring by content experts Pumps run during daylight hours only	Low	Unlikely	Low
Statutory non-compliance (Mining)	Mining Engineering Manager in caretaker mode (not appointed at present) Statutory checks in current Care and Maintenance MOP EPL in place Current SHMS	Minor	Unlikely	Low
No appointment of statutory roles	Resource for role being sourced Appointment pending operator arrangement Previous MEM still engaged onsite	Moderate	Unlikely	Medium
Energised equipment	Current SHMS (isolation) Restricted access to site Contractor management	Major	Unlikely	High
Mine subsidence	Mine subsidence plan Regular inspections Fenced off and signposted	Minor	Unlikely	Low
Bushfire & fire	Bushfire Management Plan Fire extinguishers onsite Regional bushfire brigade Fire trail access Regular inspections	Major	Unlikely	High
Vehicle interaction onsite	Traffic Management Plan in place Restricted access to site (in care and maintenance) Authorised to drive onsite	Major	Unlikely	High
Spontaneous combustion and monitoring	Pumping water underground Plan of works to manage spon com Restricted access Inspections Remedial work of known spon com areas Gas monitoring when active	Low	Unlikely	Low

Statutory non-compliance (environmental)	Checks in current Care and Maintenance MOP EPL in place Current SHMS Environmental management plan Monitoring programs Annual Environmental audits	Minor	Unlikely	Low
Personal injury from working alone	Restricted access to inducted and persons familiar with site Phone coverage available in majority of areas of pit Supervision Stay in main areas of the site	Minor	Unlikely	Low
Personal injury from Working at heights	No WAH tasks onsite identified, if so, complete JSA and be competent as per current SHMS	Low	Rare	Low
Lack of rescue and treatment of person who suffers injury	First aid kits available onsite - vehicle, first aid rooms and kitchen Mines rescue not currently needed onsite as in care and maintenance Local emergency services available Mines rescue station at Lithgow if required	Low	Unlikely	Low
Personal injury from Confined spaces	No confined spaces tasks onsite identified, if so, complete JSA and be competent as per current SHMS Current confined spaces fenced and locked off	Low	Rare	Low
Personal injury from Working over water	No Working over water tasks onsite identified, if so, complete JSA and be competent as per current SHMS	Low	Rare	Low
Personal injury from Working under loads	No Working under loads tasks onsite identified, if so, complete JSA and be competent as per current SHMS	Low	Rare	Low
Weed control	Weed Management Plan in place Wheel wash	Low	Unlikely	Low
Aboriginal Heritage Disturbance	Aboriginal Heritage Management Plan	Low	Unlikely	Low
Visual pollution	Planned rehabilitation of old workings as part of Mine Closure Plan Mine in care and maintenance	Low	Unlikely	Low
Methane venting	Not a risk at this site			
Neighbours	Community Consultative Committee Meetings Noise agreements with neighbours Complaints hotline and register Site in Care and Maintenance	Minor	Possible	Medium
Exposure to Hazardous Substances	Chemwatch to manage SDS's Cabinets for storage Current SHMS PPE available	Low	Unlikely	Low
Unplanned movement	Traffic Management Plan Trained, competent and appointed personnel Restricted access to site Site in care and maintenance JSA prior to lifting onsite	Low	Unlikely	Low
Site access from public roads	Limited access to site Site in care and maintenance	Low	Unlikely	Low

Inrush of water	Not a risk at this site at present Mine in care and maintenance	Low	Rare	Low
Tyre and rim failure	Not a risk at this site at present Mine in care and maintenance	Low	Rare	Low
Overhead power lines	Traffic Management Plan Signage Site in care and maintenance	Major	Unlikely	High
Underground services	Dig permits Up to drawings of services Current SHMS Site in care and maintenance	Low	Unlikely	Low
Lack of water quality in underground workings	Monitoring and inspection of water quality Monitor any discharges out of main dam	Low	Unlikely	Low
Vermin and pest control	Baiting programs in place as required Report any signs of vermin Regular inspections of work area	Low	Unlikely	Low
Radiation source	Designated, locked, signposted storage area Radiation Management Plan	Low	Unlikely	Low

3.3 Reporting Requirements

Under the conditions of the mining leases and exploration licences, Castlereagh Coal is required to report to DRE on any non-compliance with conditions and any complaints within 7 days.

Reporting to the Environment Protection Agency (EPA) on compliance and complaints is required under EPL 10341 to be submitted with the annual return. Notification of environmental harm must be made to the EPA within 7 days of an incident occurring and a written report may be requested.

All non-compliances and complaints are reported to the Department of Planning and Environment (DPE) in the annual AEMR in accordance with the requirements of DA 200-5-2003.

3.4 Meteorological Monitoring

Castlereagh Coal is required to conduct meteorological monitoring at the site in accordance with Schedule 4, Condition 28 of DA 200-5-2003. The Cullen Valley Mine weather station is located within the training centre adjacent the compensatory habitat area. A summary of monthly meteorological monitoring results is provided in Table 6.

3.4.1 Rainfall

Cullen Valley Mine received 600.2 mm of rainfall over 147 rain days during the reporting period. The highest rainfall occurred during January and April (both 115.0 mm) and September had the lowest rainfall (11.4 mm). A summary of monthly rainfall data is provided in Table 6.

3.4.2 Temperature

Air temperature is measured at 2 m and 10 m above ground level to account for temperature inversions. The maximum temperature recorded during the reporting period was in December (-35.2°C @ 2m, 34.2°C @10m) and the lowest temperature occurred in July (-8.7°C @ 2m, -7.7°C @10m). Average monthly temperatures are summarised in Table 6.

3.4.3 Wind Speed and Direction

Wind speed and direction is shown on Wind Roses provided in **Appendix B**.

3.4.4 Humidity

The highest humidity recorded during the reporting period at Cullen Valley Mine occurred during February (89.8%) and the lowest was during December (8.6%) as shown in Table 6.

Table 6: Cullen Valley Mine weather station summary

Month	Rainfall (mm)	Cumulative Rainfall (mm)	No of rain days/month	Air temp @ 2m (°C)			Air temp @ 10m (°C)			Humidity (%)	
				Mean (Max)	Minimum	Maximum	Mean (Max)	Minimum	Maximum	Minimum	Maximum
January	115.0	115.0	15	25.9	3.7	32.1	25.0	4.3	32.2	18.6	87.0
February	42.6	157.6	11	26.2	6.2	32.6	25.2	6.7	31.6	18.1	89.8
March	27.0	184.6	9	25.2	1.2	32.9	24.3	2.6	32.2	12.6	87.8

Month	Rainfall (mm)	Cumulative Rainfall (mm)	No of rain days/month	Air temp @ 2m (°C)			Air temp @ 10m (°C)			Humidity (%)	
				Mean (Max)	Minimum	Maximum	Mean (Max)	Minimum	Maximum	Minimum	Maximum
April	115.0	299.6	20	18.3	-1.0	25.5	18.4	-0.4	24.9	31.7	87.5
May	18.6	318.2	11	15.0	-3.7	20.8	14.6	-3.2	20.2	28.9	88.1
June	28.0	346.2	13	13.4	-7.3	17.2	13.2	-6.2	17.2	18.7	87.8
July	47.6	393.8	18	11.2	-8.7	15.2	10.7	-7.7	14.9	20.9	88.2
August	33.6	427.4	11	13.4	-6.7	21.1	12.8	-5.8	20.5	26.2	88.6
September	11.4	438.8	10	17.1	-4.6	22.9	16.3	-3.9	22.2	14.5	88.3
October	14.8	453.6	9	24.3	0.0	31.0	23.2	1.8	30.0	11.0	88.2
November	83.2	536.8	11	24.8	2.1	34.3	23.7	3.3	33.3	10.4	87.7
December	63.4	600.2	9	27.5	4.3	35.2	26.3	5.1	34.2	8.6	86.5
Total	600.2		147								

3.5 Air Quality

3.5.1 Environmental Management

There were no mining activities undertaken during the reporting period, including blasting, coal and overburden haulage by trucks. As such, potential impacts to air quality were minimal. Control measures to minimise air quality impacts include limiting vehicle speeds on site and utilising a water cart on haul roads as required when undertaking care and maintenance works.

Air quality monitoring is undertaken in accordance with the Environmental Management Plan (EMP) to verify the effectiveness of air quality control measures and includes monitoring of deposited dust, particulate matter, and meteorological conditions. The air quality monitoring network consists of five dust deposition gauges and one High Volume Air Sampler (HVAS) measuring particulate matter <10µm (PM₁₀). Monitoring locations are shown on **Figure 5, Appendix A**.

Air quality impacts at Cullen Valley Mine are managed in a manner that minimises generation of airborne and visual dust. The control strategies outlined in the EMP are considered adequate to manage risks associated with air pollution.

3.5.2 Environmental Performance

Castlereagh Coal is required to ensure that dust and particulate emissions do not cause exceedences of the criteria specified by the development approval (DA 200-5-2003). The air quality impact assessment criteria specified in DA 200-5-2003 are provided in Table 7.

Table 7: Air quality impact assessment criteria

Pollutant	Averaging Period	Criterion
Total suspended particulate (TSP) matter	Annual average	90 µg/m ³
Particulate matter <10µm (PM ₁₀)	Annual average	30 µg/m ³
	24 hour average	50 µg/m ³
Deposited dust	Annual average (maximum total)	4 g/m ² /month
	Annual average (maximum increase)	2 g/m ² /month

Deposited dust is monitored on a monthly basis at five representative locations around the mine site (dust deposition gauges CDD1 to CDD5). The annual average criterion for deposited dust (4g/m²/month) was not exceeded at any of the dust deposition gauges during 2015. The increase in annual average dust levels was less than the criterion of 2g/m²/month at all gauges

except CDD2. This is attributed to an elevated dust result in May 2015 which was contaminated with insects and bird droppings. The deposited dust monitoring results for 2015 and annual averages are shown in Table 8.

Table 8: Deposited dust monitoring results

Date	Total Insoluble Solids (g/m ² /month)				
	CDD1	CDD2	CDD3	CDD4	CDD5
January 2015	0.3	0.2	0.6	2.2	1.6
February 2015	0.1	0.8	0.6	1.9	0.9
March 2015	0.2	0.7	0.4	1.0	0.8
April 2015	<0.1	<0.1	<0.1	<0.1	<0.1
May 2015	<0.1	16.3	0.7	0.4	0.6
June 2015	0.4	0.2	<0.1	0.2	0.4
July 2015	<0.1	<0.1	<0.1	0.1	0.3
August 2015	0.4	1.7	0.4	0.4	0.8
September 2015	0.5	6.6	0.5	0.9	1.0
October 2015	0.4	5.3	0.1	0.8	0.3
November 2015	0.3	0.2	0.6	0.8	0.4
December 2015	0.2	0.5	0.8	0.5	0.3
Annual Averages					
2012	1.0	1.1	0.6	0.5	0.9
2013	0.8	0.5	0.5	0.4	0.6
2014	2.0	0.8	1.0	0.6	19.2
2015	0.3	3.3	0.5	0.8	0.7

Monitoring of particulate matter is conducted on a 24-hour basis (recorded continuously and collected weekly) using a HVAS located within the Cullen Valley Mine site. Total suspended particulates are estimated from the PM₁₀ concentrations. The annual average criteria for PM₁₀ (30 µg/m³) and TSP (90 µg/m³) were not exceeded during the 2015 reporting period. The 24 hour maximum allowable limit for PM₁₀ (50µg/m³) was not exceeded during the reporting period. The particulate matter monitoring results and annual averages for 2015 are shown in Table 9.

Table 9: Particulate matter (PM₁₀) and Total suspended particulates (TSP) results

Monthly average	PM ₁₀ (µg/m ³)	TSP (µg/m ³)
January 2015	2.7	6.7
February 2015	7.3	18.1
March 2015	10.2	25.5
April 2015	2.0	5.0
May 2015	26.0	65.0
June 2015	2.5	6.3
July 2015	4.4	11.0
August 2015	6.0	15.0
September 2015	6.0	15.0
October 2015	11.0	27.5
November 2015	9.4	23.5
December 2015	19.3	48.3
Annual Average 2015	8.4	21.0

3.5.3 Reportable Incidents

Monitoring of air quality at Cullen Valley Mine is conducted in accordance with the EMP by RCA Laboratories. Monitoring results and compliance with the development approval conditions are reported on a monthly basis. A summary of monthly monitoring results are provided on the Castlereagh Coal website.

Where exceedences of the impact assessment criteria are detected, these will be reported to the Director General within 24 hours. It should be noted that there were no mining operations

conducted during the 2015 reporting period. There were no exceedences of the conditions of the development approval except for an increase in the annual average dust at CDD2 which can be explained by contamination of the gauge with insects and bird droppings

3.5.4 Further Improvements

Monitoring of air quality will continue to be conducted during the care and maintenance phase in accordance with the approved EMP to ensure compliance with the conditions of the development approval. Air quality monitoring equipment and weather stations are regularly inspected, calibrated and maintained as required to ensure optimum operation.

3.6 Erosion and Sedimentation

3.6.1 Environmental Management

Permanent erosion and sediment control measures (ESC) within the Cullen Valley Mine include containment and diversion of “clean” water around disturbed areas and containment of runoff from these disturbed areas within on-site sediment dams. Temporary measures include contour banks, drainage lines, and silt-stop fences. All ESC measures are installed and maintained in accordance with the EMP.

3.6.2 Environmental Performance

Erosion control structures are inspected on a regular basis and repairs undertaken as required. Maintenance and repairs were undertaken on erosion and sediment controls located in rehabilitation areas during the 2015 reporting period. These included:

- Cleaning out and repair of contour drains to achieve required fall and reconstruction of drain walls where required; and
- Repair of eroded slopes and reducing water flow rates to prevent further washouts.

A site inspection was conducted of erosion and sediment control devices in rehabilitation areas and subsurface heating areas by Sedgman’s Principal Civil Engineer on 29th October 2015. This site inspection was conducted to determine remedial actions required to prevent further accelerated deterioration of existing erosion and sediment control (ESC) measures in place at Cullen Valley Mine.

It was noted that the worst erosion occurs at the northern end of the mine where larger and steeper catchments are producing runoff to constructed stormwater improvement devices. The following issues relating to existing control devices were identified:

1. Side slope catchment drains have insufficient gradients to allow self-scouring and prevent sediment buildup;
2. V-shaped contour drains at the northern end of the mine are incapable of accommodating flows from upstream catchments;
3. Existing rock flumes on embankments have failed because of poor rock selection, lack of geofabric underlay, poor entry type and geometry; and
4. A recently reconstructed catch drain is causing “breakout” of runoff and overtopping.

Repair of these ESC measures will be undertaken in the next reporting period.

In addition to maintaining ESC measures, Castlereagh Coal is required to ensure that water discharged from the site does not exceed the pollutant concentration limits specified by the environmental protection licence (EPL 10341) and DA 200-5-2003. The concentration limits specified in EPL 10341 and DA 200-5-2003 are provided in Table 10.

Table 10: Water quality concentration limits

Pollutant	Concentration limit
Oil & Grease	10 mg/L
pH	6.5 – 8.5
Total suspended solids (TSS)	30 mg/L

Monitoring of water quality has been conducted only during discharge of water at the licenced discharge points (LD001 and LD004) between January and November. There were no discharges of water from LD001 or LD004 during this period.

Monthly monitoring of water quality within Dam 1 and Dam 4 commenced in December 2015 and will continue on a monthly basis regardless of whether water is discharged from the licenced discharge points. The water quality monitoring results from these dams are shown in Table 11.

Table 11: Water quality monitoring results within site dams 11 December 2015

Water storage dam	Oil & Grease	pH	TSS
Dam 1	<2 mg/L	8.25	11 mg/L
Dam 4	<2 mg/L	7.81	<5 mg/L

Water quality limits are not specified in the licence for Dams 1 and 4. The pH in these dams is considered generally neutral. The TSS concentration of both dams is considered to be relatively low and the oil and grease concentrations are below detection limits.

3.6.3 Reportable Incidents

ESC measures are maintained in accordance with the EMP to minimise transport of sediment to downstream waters. Water quality monitoring results and compliance with the licence conditions are reported on a monthly basis and are reported to EPA with the licence Annual Return. A summary of monthly monitoring results is provided on the Castlereagh Coal website.

There were no discharge events from Dam 1 and Dam 4 during the 2015 reporting period and there were therefore no reportable incidents.

3.6.4 Further Improvements

Monitoring of water quality will continue to be conducted during the care and maintenance phase to ensure compliance with the licence conditions. ESC measures are regularly inspected and repairs undertaken as required. Further improvements to be undertaken to ESC measures following the site inspection on 29 October 2015 include:

- Reconstruction of side slope catch drains to achieve at least a 1 to 1.5% gradient;
- Reconstruction of contour drains to a 3.0 m width base profile;
- Reconstruction of existing rock flumes on embankments and construction of a “stilling pond”; and
- Additional remedial work on the recently reconstructed catch drain to prevent the “breakout” of runoff from overtopping.

Additional monitoring of Dams 1 and 4 commenced in December 2015 and will continue on a monthly basis regardless of discharge from the licenced discharge points.

3.7 Surface Water

3.7.1 Environmental Management

The surface water management system at Cullen Valley Mine is a closed loop system that utilises a series of settlement dams within the site. These dams are managed in accordance with the EMP as described in Section 2.8. Water is only discharged from the licenced discharge points if water quality concentration limits specified in EPL 1095 and DA 200-5-2003 are achieved (refer to Table 10).

Water quality monitoring is conducted monthly during any discharge from the licenced discharge points. Water quality is also monitored on a monthly basis at two downstream locations (BSW01 and BSW02) as shown on **Figure 5, Appendix A**. Water quality monitoring also commenced in December 2015 at the Hillcroft Property (BSW03) which will continue to be monitored on a monthly basis.

3.7.2 Environmental Performance

There were no discharge events from the licenced discharge points during the 2015 reporting period.

The water quality results recorded within downstream creeks and the Hillcroft Property are provided in Table 12. Water quality limits are not stipulated in the licence for the downstream surface water monitoring locations. However, pH results are considered generally neutral, except for the October pH measurement at BSW01, which was slightly acidic. TSS concentrations are considered low and the concentration of oil and grease at both downstream locations were below laboratory detection limits.

Table 12: Water quality monitoring results at downstream creeks (BSW01 and BSW02) and the Hillcroft Property (BSW03)

Sampling date	Oil & grease	pH	TSS
Monitoring location BSW01			
5 August 2015	<2 mg/L	7.6	12 mg/L
8 September 2015	<2 mg/L	6.59	15 mg/L
9 October 2015	<2 mg/L	6.09	19 mg/L
10 November 2015	<2 mg/L	7.60	19 mg/L
10 December 2015	<2 mg/L	7.09	29.5 mg/L
Monitoring location BSW02			
5 August 2015	<2 mg/L	8.18	<5 mg/L
8 September 2015	<2 mg/L	8.07	5 mg/L
9 October 2015	<2 mg/L	7.76	<5 mg/L
10 November 2015	<2 mg/L	7.65	<5 mg/L
10 December 2015	<2 mg/L	7.83	19.0 mg/L
Hillcroft Property BSW03			
10 December 2015	<2 mg/L	7.70	11 mg/L

3.7.3 Reportable Incidents

Water quality monitoring results and compliance with the licence conditions are reported on a monthly basis and are reported to EPA with the EPL 10341 Annual Return. A summary of monthly monitoring results are provided on the Castlereagh Coal website.

There were no discharges from licenced discharge points during the 2015 reporting period and there were therefore no reportable incidents.

3.7.4 Further Improvements

Monitoring of water quality will continue to be conducted during the care and maintenance phase to ensure compliance with the licence conditions. The water management system is regularly inspected and repairs undertaken as required.

Water quality monitoring also commenced in December 2015 at the Hillcroft Property (BSW03) which will continue to be monitored on a monthly basis.

3.8 Ground Water

3.8.1 Environmental Management

The mining operation is located on the western escarpment of the Sydney Basin and groundwater intercepted from monitoring bore holes is typically greater than 70m depth. The open cut voids at the Cullen Valley Mine are less than this depth and generally do not intercept any natural groundwater aquifers. Therefore no specific environmental management controls are considered necessary for groundwater management.

3.8.2 Environmental Performance

Baseline groundwater monitoring has been undertaken in 6 rounds of sampling at 7 monitoring bores between 2011 and 2014. Groundwater monitoring locations are shown on **Figure 5, Appendix A**. Following the 2014 monitoring event conducted by Environment & Natural Resource Solutions, the following conclusions were made regarding groundwater:

- There were no significant changes in Standing Water Level in monitoring bores since the previous monitoring event. The groundwater levels range between 864.8 mAHD in CP131 and 895.5 mAHD in BHW1;
- Salinity remains relatively fresh at the site with concentrations below 1,000 µS/cm. Salinity results are below the ANZECC guideline for 95% protection of species;
- Field results recorded a range in pH between 5.97 (CP116) and 7.36 (BHW1). pH has declined since the previous monitoring event, however results are generally within the range of historical values and are characteristic of groundwater conditions in the area. A moderate increase in pH was observed in BHW1. Low pH in groundwater in the area is expected to represent naturally occurring background conditions associated with silica saturation and oxidation of accessory marcasites grains (iron sulphide) within the weathered sandstone;
- Hardness values are reported between 43 mg/L (LD001) and 350 mg/L (CP115). The majority of Site waters may be classified as moderate to very hard. Results for hardness are relatively consistent at the Site with the exception of CP115 which has consistently increased from 130 mg/L in August 2011 to 350 mg/L in July 2014;
- Concentrations of Nitrate and Sulphate are relatively stable in the majority of bores. However, it is noted that levels in CP115 have decreased since the previous monitoring event where results have previously been increasing since February 2013; and
- Concentrations of heavy metals and metalloids in groundwater at the Site report variable concentrations. Increased levels of Cadmium and Iron were reported in bores at the Site during the July 2014 monitoring event. It is noted that elevated levels of metals may be the result of lower pH at the Site which can increase the solubility of heavy metals.

A further round of groundwater monitoring was conducted by RCA on 10 November 2015. The results of groundwater monitoring conducted during the 2015 reporting period are provided in Table 13.

Table 13: 2015 groundwater monitoring results

Sample site	CP114	CP115	CP116	CP131	CP132	LD001	BHW1
Sample date	10/11/15	10/11/15	10/11/15	10/11/15	10/11/15	10/11/15	10/11/15
AHD (RL) (m)	869.75	893.82	892.20	864.76	887.50	890.30	895.21
Depth to aquifer (m)	35.37	56.13	49.04	73.37	17.23	49.82	44.10
pH	6.36	6.28	6.39	Well dry	6.71	7.15	7.09
Electrical Conductivity (µS/cm)	301	757	588		403	155	453
Nitrite (mg/L)	<0.005	<0.005	<0.005		<0.005	<0.005	<0.005
Total Oxidised Nitrogen (mg/L)	0.040	<0.005	<0.005		0.006	0.22	0.006
Chloride (mg/L)	16	3.2	20		33	5.3	24
Nitrate (mg/L)	0.039	<0.005	<0.005		<0.005	0.22	<0.005
Sulphate (mg/L)	16	350	140		26	14	4.9
Alkalinity (mg/L)	110	56	160		110	44	200
Calcium (mg/L)	26	89	34		33	11	42
Magnesium (mg/L)	11	33	10		15	4.0	18
Sodium (mg/L)	14	16	66		11	5.4	9.6
Potassium (mg/L)	6.0	10	7.0		8.8	6.7	8.8
Total Hardness (mg CaCO ₃ /L)	110	360	130		140	44	180
Aluminium (µg/L)	35	47	7		33	26	37
Arsenic (µg/L)	<1	<1	<1		<1	<1	<1
Cadmium (µg/L)	<0.1	<0.1	<0.1		<0.1	<0.1	0.3
Chromium (µg/L)	<1	<1	<1		1	<1	<1
Copper (µg/L)	5	<1	<1		<1	23	<1
Iron (µg/L)	<5	8500	5100		4200	21	4000
Lead (ug/L)	<1	<1	<1		<1	<1	<1
Manganese (ug/L)	940	420	670		140	1	200
Molybdenum (ug/L)	<1	7	<1		1	<1	<1
Nickel (ug/L)	27	76	17		6	10	14
Selenium (ug/L)	<1	<1	<1		<1	<1	<1
Zinc (ug/L)	10	21	11		11	100	11000
Mercury (mg/L)	<0.0001	<0.0001	<0.0001		<0.0001	<0.0001	<0.0001

Conclusions made following the most recent groundwater monitoring conducted by RCA are as follows:

- No significant changes were observed in standing water levels (also refer to **Figure 1** below);
- Salinity remains relatively fresh and results for EC are below the ANZECC guideline for 95% protection of species;
- The pH at bores LD001, CP114, CP116 and CP132, has increased slightly since the July 2014 monitoring event, however results remain within the range of historical values and characteristic of groundwater conditions in the area. A slight decrease was observed in BHW1, whilst the pH at CP115 remained stable;
- The majority of Site waters may be classified as moderate to very hard. Results for hardness within the bores are relatively consistent across the Site;
- Concentrations of Sulphate have remained stable in bores LD001 and CP114; whilst a slight decrease was observed in bores CP132 and BW01. Sulphate concentrations in bore CP116 has increased since the last monitoring round in July 2014, however the concentration remains within historical levels;
- The Concentrations of Nitrate were observed to have decreased to below laboratory detection limits in bores CP115, CP116, CP132 and BHW1; whilst bore LD001 has remained stable. A slight increase was observed in bore CP114, however all concentrations continue to remain within historical levels; and

- Concentrations of heavy metals and metalloids were consistent with historical monitoring results. Concentrations of Cadmium and Iron have now either reduced, or remained stable; with the exception of bore LD001 and BHW1. An increase in Iron was observed in LD001, whilst an increase in both Iron and Cadmium was observed in BHW1. It should be noted that elevated levels of metals may be the results of a reduction in the pH at BWH1 which can increase the solubility of heavy metals.




Figure 1: Standing water levels in groundwater bores

3.8.3 Reportable Incidents

Open cut voids at the Cullen Valley Mine are less than the depth of groundwater levels at the site and mining operations generally do not intercept any natural groundwater aquifers. There have been no impacts detected to groundwater quality and there were therefore no reportable incidents.

3.8.4 Further Improvements

There have been no impacts detected on groundwater levels and water quality at Cullen Valley Mine and therefore no further improvements are proposed.

3.9 Contaminated Land

3.9.1 Environmental Management

There are no known areas of land contamination within the Cullen Valley Mine site. There were no works undertaken during the reporting period that may cause significant land contamination. Control measures are in place for management of hazardous materials that may cause land contamination.

The majority of hazardous materials were removed from site at the commencement of the care and maintenance period. One self-bunded 75,000L diesel tank is currently maintained at the site. This tank is currently not used, but may be used to store a maximum of 35,000L fuel for pumps, heavy equipment and light vehicles if environmental maintenance work is performed..

A small amount of diesel was delivered to site for pumping during the 2015 reporting period. In addition, waste oil and grease is stored adjacent to the workshop in a bunded area which is regularly removed by a licensed contractor, along with oily water from the oil and water separator as required.

3.9.2 Environmental Performance

There was no mining disturbance during the reporting period and as such no specific management controls or monitoring procedures were required. No reportable hydrocarbon spills or other incidents requiring disposal of contaminated material occurred during the reporting period.

3.9.3 Reportable Incidents

There are no known areas of land contamination within the Cullen Valley Mine site. There were no incidents of land contamination due to storage and handling of hazardous materials during the 2015 reporting period.

3.9.4 Further Improvements

Hazardous substances and land contamination will continue to be managed in accordance with the licence conditions and the C&M MOP. Should significant risks be identified or where reportable incidents occur, environmental control measures will be reviewed and additional controls implemented as required.

3.10 Threatened Flora and Fauna

3.10.1 Environmental Management

Existing vegetation communities and fauna habitat have previously been characterised during the ecological impact assessment (Cumberland Ecology 2014) conducted for the Environmental Assessment. Site environmental values are assessed during annual biodiversity monitoring of the rehabilitation and offsets areas in accordance with the Flora and Fauna Management Plan and the Environmental Monitoring Program.

3.10.2 Environmental Performance

There were no vegetation removal or land clearing activities conducted during the 2015 reporting period. No new rehabilitation areas were established and rehabilitation works focused on remediation of failed vegetation in existing rehabilitation areas. Remediation of existing rehabilitation areas is conducted generally in accordance with the approved Flora and Fauna Management Plan and are detailed in Section 5.

3.10.3 Reportable Incidents

There were no vegetation removal or land clearing activities during the 2015 reporting period and no significant impacts to environmental values were detected during the annual biodiversity monitoring conducted in November 2015. Therefore there were no reportable incidents during the 2015 reporting period.

3.10.4 Further Improvements

Environmental values will continue to be managed and annual monitoring conducted in accordance with the Flora and Fauna Management Plan and the Environmental Monitoring Program. It is expected that the management plans and programs for the Cullen Valley Mine will

be reviewed and updated during the approvals process prior to re-commencement of mining operations.

3.11 Weeds

3.11.1 Environmental Management

Weed management is conducted in accordance with the Landscape Management Plan and spraying is targeted towards known weed species occurrences within the site.

A weed spraying program was developed and implemented by licenced weed spraying contractor, Kleinfelder. An initial round of weed spraying was conducted for 5 days during November commencing on 2 November 2015 to control weed infestations identified within the site.

The initial round of weed spraying was conducted prior to the annual biodiversity monitoring and then a second round of targeted spraying is being conducted on 18 January 2016 following feedback of the locations and extent of weed infestations detected during annual monitoring.

A Weed Identification Kit has been developed and is held on site to assist on-site personnel in recognizing noxious weeds within the site. Weed infestations detected by site personnel are reported to the weed spraying contractor.

3.11.2 Environmental Performance

The weed spraying program indicated that the most abundant weed infestations within the site were:

- Black Berry (*Rubus fruticosus*);
- St. John's Wort (*Hypericum perforatum*);
- Briar Rose (*Rosa rubiginosa*); and
- Broom (*Cytisus* sp.).

These species were targeted during 2015 and are being controlled through implementation of the weed spraying program conducted by Kleinfelder.

3.11.3 Reportable Incidents

Weed spraying locations are recorded during the weed spraying program and during annual biodiversity monitoring and are reported annually. There were no reportable incidents in relation to weed management during the 2015 reporting period.

3.11.4 Further Improvements

The weed spraying program will continue to be conducted on an annual basis. Future weed spraying will be conducted during spring and summer and will target those species known to occur within the site as indicated by annual biodiversity monitoring.

3.12 Blasting

3.12.1 Environmental Management

Blasting is managed and monitored in accordance with the Blast Management Plan (BMP) and the conditions of EPL 10341. However, as no mining operations were undertaken, no blasting was conducted during the 2015 reporting period.

3.12.2 Environmental Performance

Limits for airblast overpressure and ground vibration peak particle velocity from blasting operations are specified in EPL 10341 as outlined in Table 14.

Table 14: Blasting impact assessment criteria

Criteria	Limit	Allowable exceedence
Airblast overpressure level	115 dB(Lin Peak)	Must not be exceeded at any noise sensitive locations for more than 5% of the total number of blasts over a period of 12 months
	120 dB(Lin Peak)	Must not be exceeded at any time at any noise sensitive locations
Peak particle velocity	5 mm/s	Must not be exceeded at any noise sensitive locations for more than 5% of the total number of blasts over a period of 12 months
	10 mm/s	Must not be exceeded at any time at any noise sensitive locations

Blast monitoring is conducted during all blasting operations in accordance with the BMP and EPL 10341. However, no blasting was conducted during the 2015 reporting period

3.12.3 Reportable Incidents

All blast monitoring results are recorded by the blasting contractor and records are maintained at the site office and made available to statutory agencies on request. As there was no blasting conducted, there were no non-compliances with the licence conditions and therefore no reportable incidents during the 2015 reporting period.

3.12.4 Further Improvements

Where monitoring indicates non-compliance with the licence conditions, additional control measures will be implemented as required. However, no blasting was conducted during the 2015 reporting period and no improvements are currently required.

3.13 Operational Noise

3.13.1 Environmental Management

There were no mining operations during the 2015 reporting period, however, quarterly attended monitoring was conducted by Global Acoustics at five locations around the site during care and maintenance activities.

3.13.2 Environmental Performance

Noise impact assessment criteria for monitoring as specified in DA 200-5-2003 are outlined in Table 15.

Table 15: Noise impact assessment criteria DA 200-5-2003

Location	Day – LAeq (15 minute)	Evening – LAeq (15 minute)	Night – LAeq (15 minute)	Night - LA1 (1 minute)
Red Springs (east of rail line)	37 dB(A)	35 dB(A)	35 dB(A)	45 dB(A)
Red Springs (west of rail line)	43	38	35	45
Hillcroft (east of rail line)	35	35	35	45
Hillcroft (west of rail line)	43	38	35	45
Forest Lodge	40	40	38	45
Doble Gate	43	38	35	45
Tilley	43	38	35	45

Noise impact assessment criteria for monitoring as specified in EPL 10341 are outlined in Table 16.

Table 16: Noise impact assessment criteria EPL 10341

Location	Day – LAeq (15 minute)	Evening – LAeq (15 minute)	Night – LAeq (15 minute)	Night - LA1 (1 minute)
Red Springs (east of rail line)	35 dB(A)	35 dB(A)	35 dB(A)	45 dB(A)
Red Springs (west of rail line)	43	38	35	45
Hillcroft (east of rail line)	35	35	35	45
Hillcroft (west of rail line)	43	38	35	45
Forest Lodge	40	40	40	45
Doble Gate	43	38	35	45
Tilley	43	38	35	45

As there are no evening or night time activities conducted during the care and maintenance period, attended monitoring was conducted at five locations during the day period only. The results of quarterly attended noise monitoring are outlined in Table 17. There were no exceedences of the impact assessment criteria (where applicable) detected during quarterly monitoring conducted during the 2015 reporting period.

Table 17: Quarterly attended noise monitoring results

Location	Start Date and Time	Vertical temperature gradient (°C/100m)	Wind speed (m/s)	Cullen Valley Mine noise	L _{Aeq} (dB)
Quarter 1					
Red Springs	36 March 2015 07:00	-2.0	0.0	Inaudible	42 [#]
Hillcroft	36 March 2015 07:14	-2.0	0.0	Inaudible	34
Forest Lodge	36 March 2015 07:43	-2.0	0.0	Inaudible	40
Doble Gate	36 March 2015 08:05	-2.0	0.0	Inaudible	64 [#]
Tilley	36 March 2015 08:19	-2.0	0.0	Inaudible	66 [#]
Quarter 2					
Red Springs	22 June 2015 14:06	-2.0	6.2	Inaudible	32
Hillcroft	22 June 2015 14:29	-2.0	7.7	Inaudible	39*
Forest Lodge	22 June 2015 14:56	-2.0	6.2	Inaudible	28
Doble Gate	22 June 2015 12:16	-2.0	5.1	Inaudible	49*
Tilley	22 June 2015 12:37	-2.0	6.7	Inaudible	69*
Quarter 3					
Red Springs	20 August 2015 09:53	-2.0	0.5	Inaudible	43
Hillcroft	20 August 2015 09:53	-2.0	2.1	Inaudible	35
Forest Lodge	20 August 2015 09:53	-2.0	2.6	Inaudible	40
Doble Gate	20 August 2015 09:53	-2.0	2.1	Inaudible	51 [#]
Tilley	20 August 2015 09:53	-2.0	2.6	Inaudible	66 [#]
Quarter 4					
Red Springs	2 December 2015 14:23	-2.0	6.7	Inaudible	41
Hillcroft	2 December 2015 14:40	-2.0	4.6	Inaudible	38

Location	Start Date and Time	Vertical temperature gradient (°C/100m)	Wind speed (m/s)	Cullen Valley Mine noise	L _{Aeq} (dB)
Forest Lodge	2 December 2015 15:06	-2.0	4.1	Inaudible	42
Doble Gate	2 December 2015 15:32	-2.0	8.2	Inaudible	49
Tilley	2 December 2015 15:50	-2.0	7.2	Inaudible	69

**Noise from the Cullen Valley Mine was determined by Global Acoustics to be inaudible at the time of monitoring and there was therefore no exceedance of the licence limits.*

**Noise measurements are affected by wind speed (over 3m/s²) and vertical temperature gradient (over 3°C/100m). As wind speeds of over 3m/s² were measured at these locations at the time of monitoring, Global acoustics determined that the impact assessment criteria did not apply.*

3.13.3 Reportable Incidents

Where an exceedance of the impact assessment criteria is detected during monitoring, Castlereagh Coal will notify the Director-General and affected landowners except where there is a negotiated agreement with landowners. As there were no noise limit exceedances detected during quarterly monitoring, there were no reportable incidents.

3.13.4 Further Improvements

Where non-compliance with approval and licence conditions is detected or noise complaints are received, corrective actions will be implemented as required. As there were no non-compliances or complaints received during the 2015 reporting period, no further improvements are required.

3.14 Visual, Stray Light

3.14.1 Environmental Management

The open cut operations at Cullen Valley Mine are visible from Portland Road and Red Springs Road. However, progressive backfilling and revegetation of these areas has seen it progressively blending with the surrounding landscape.

Minimal lighting is used at Cullen Valley Mine while in care and maintenance. Any lighting required is for safety and emergency purposes only and is implemented on an as needs basis. As such there are very low potential impacts from lighting while in care and maintenance.

Main flood lights and any portable lights are directed away from nearby residences and the Castlereagh Highway. Flood lights attached to towers, are adjustable to enable modification of light direction and placement. All lighting is directed to minimise extraneous light within the catchment.

3.14.2 Environmental Performance

Castlereagh Coal is required to ensure that all external lighting complies with *Australian Standard AS4282 (INT) 1995 – Control of Obtrusive Effects of Outdoor Lighting* under the conditions of DA 200-5-2003. Light levels were reduced during the 2015 reporting period as there were no mining operations conducted.

3.14.3 Reportable Incidents

There were no non-compliances with DA 200-5-2003 and no complaints received in relation to visual impacts of lighting and there were therefore no reportable incidents during the 2015 reporting period.

3.14.4 Further Improvements

Where visual impacts of lighting are detected, Castlereagh Coal will implement corrective actions as required. As there were no non-compliances or complaints during the 2015 reporting period, no further improvements are required.

3.15 Aboriginal Heritage

3.15.1 Environmental Management

Previous archaeological surveys did not locate any Aboriginal Artefacts or sites within the approved open cut mining area. However, two sites of significance were recorded in close proximity to the approved mining area. A campsite-stone artefact scatter (C-OS-1) and a rock shelter site (C-S-1). A further two sites were identified in surveys undertaken during 2011 and include 45-1-2542 and RSC-OS-1. These sites are located outside of the existing mining area and will not be impacted.

In the unlikely event that disturbance to the sites is required, an appropriate investigation of the open camp and site scatter would be undertaken by an appropriately qualified archaeologist in consultation with relevant stakeholders including Aboriginal groups. If any further Aboriginal objects are uncovered at any time, the Office of Environment and Heritage (OEH) will be notified accordingly.

3.15.2 Environmental Performance

There was no disturbance of Aboriginal heritage sites during the 2015 reporting period. There were no vegetation clearing or ground disturbance works conducted in previously undisturbed areas during the 2015 reporting period. Where vegetation clearing or ground disturbance works uncover previously unrecorded objects of Aboriginal heritage, this would be reported to the Aboriginal party and OEH.

3.15.3 Reportable Incidents

No disturbance of Aboriginal heritage sites occurred and no vegetation clearing or ground disturbance works were conducted in previously undisturbed areas and there were therefore no reportable incidents during the 2015 reporting period.

3.15.4 Further Improvements

Where disturbance of Aboriginal heritage values occurs, corrective actions will be implemented as required. As there were no impacts on Aboriginal heritage during the 2015 reporting period, no further improvements are required.

3.16 European Heritage

3.16.1 Environmental Management

The most important site of European heritage significance is the Cullen Bullen General Cemetery, which demonstrates a wide range of approaches to funerary memorials throughout the twentieth century. Monuments contained within the cemetery display a variety of interpretations on the more sophisticated contemporary styles and the site includes a number of unusual features including concrete pyramids which mark denominational sections. The graves marked with sandstone drill core sections provide an indication of the importance of mining to this rural community. Other items of heritage significance in the local area include the Coach House and Back Cullen Cemetery.

No mining activities or exploration works were undertaken in proximity of locations of European heritage significance.

3.16.2 Environmental Performance

No items of European heritage are likely to be disturbed during site operations and no specific management measures are required.

3.16.3 Reportable Incidents

No items of European heritage were disturbed during the 2015 reporting period and there were therefore no reportable incidents.

3.16.4 Further Improvements

No specific management measures for European heritage are implemented for the site and no further improvements are currently required.

3.17 Spontaneous Combustion and Subsurface Heating

Stockpiled coal and in-situ coal resources at Cullen Valley Mine have a low propensity to spontaneously combust. However, to ensure that it is not relevant to the subsurface heating issue, a study was undertaken to supplement the existing knowledge of the spontaneous combustion propensity of the coal and overburden in the backfill.

The results detailed in a report by RGS Environmental (May 2013) have confirmed that the in-situ coal is 'low-risk' for spontaneous combustion and there is a very low potential for spontaneous combustion to be a contributing factor to the initiation and spread of subsurface heating at Cullen Valley Mine.

3.17.1 Environmental Management

A comprehensive assessment of sub-surface heating at the Cullen Valley Mine has been undertaken in consultation with DRE. The PoW MOP Variation (dated 30 January 2013) was prepared following site assessments of the subsurface heating area by Olsen Consulting Group (OCG). The PoW MOP Variation was approved by DRE on 11 March 2013. The approved PoW MOP Variation details the history, proposed management and mitigation strategies and schedule of works proposed to treat the heat affected area. A copy of the approved PoW MOP Variation is provided in the Draft Cullen Valley C&M MOP.

A further site assessment was conducted by OCG on 29 October 2015 to provide an update on subsurface heating issues at Cullen Valley Mine.

3.17.2 Environmental Performance

The assessment of subsurface heating areas noted that:

- Previously capped areas continue to show no evidence of reheating indicating that capping provides a potential treatment for the remaining heating areas;
- Heating affected vegetation adjacent previously capped areas had increased and showed evidence of combustion – actions required to address this combustion;
- Level of obvious heating on the steep face above the haul road has continued to decrease and vegetation has continued to improve but there is still thermal activity on the western edge – monitoring is required and containment of further extension of heating to the west;

- Backfilled areas along the interface of the highwall and overburden showed much less emissions than previously and this practice should be continued
- The area adjacent to the haul road that was previously treated by extracting heating material and replacing with inert clay and stone has worked successfully with no obvious indication of reheating. The remaining heating in this area had increased slightly in size and treatment is required for containment of further extension of heating to the west;
- The treated noise bund wall showed no obvious signs of reheating.

Feedback from OCG following this site inspection was that treatment should focus on containment of the remaining heating areas and areas where vegetation dieback and smoke emanation indicate continued subsurface heating.

Subsurface heating area monitoring locations are shown on **Figure 6, Appendix A**.

3.17.3 Reportable Incidents

Development of management measures implemented for rectification of subsurface heating issues were undertaken in consultation with DRE. The recommendations of the site assessment and Subsurface Heating Program of Works were provided to the Department for review and approval with the Draft Cullen Valley C&M MOP.

3.17.4 Further Improvements

The recommendations arising from this site assessment are as follows:

- Further monitoring and observations of heating areas should continue to confirm the appropriate level of heating management;
- Capping of heating areas should be continued as a management strategy. Continue monitoring of treated areas to record success or identify the need to modify actions;
- Treatment of vegetation die back in heating areas should include water management to ensure overland water flow does not enter the site. Initial investigation could include a trench excavated at the active front of the heated area to assist in planning a suitable response;
- Remaining heating areas could be treated by removal of heating material and substitution with inert clay and rock (if available);
- Martin Olsen should be onsite when any recommended treatments are undertaken to enable direct input into the team managing the day to day activities; and
- The current PoW MOP Variation should be amended to reflect changes as a result of care and maintenance activities.

The monitoring and rectification works in subsurface heating areas recommended by the OCG site assessment will be conducted in accordance with the PoW MOP Variation and Subsurface Heating Program of Works.

3.18 Bushfire

3.18.1 Environmental Management

A Bushfire Management Plan has been developed in consultation with the Forestry Corporation NSW. A number of measures and safeguards have been implemented to minimise bushfire risk. These include:

- Fitting fire extinguishers to all earthmoving and mining equipment;
- Fitting and maintaining efficient exhaust systems and spark arresters to mobile equipment;

- Advising NSW Rural Fire Service, regulatory authorities and neighbours of any burning-off operations;
- Ensuring that vehicles with low level exhaust systems do not leave defined tracks in locations and conditions likely to lead to ignition of combustible plant material; and
- Maintaining, at the request of NSW Forestry Corporation, existing fire trails or access roads at the extremities of the lease area, which serve as access for fire fighting services as well as establishing a fire break to the limits of operations at the open cut.

3.18.2 Environmental Performance

There were no bush fire events at Cullen Valley Mine or any events adjacent to the site during the reporting period.

3.18.3 Reportable Incidents

There were no bushfire events on or adjacent to the Cullen Valley Mine site and therefore no reportable incidents during the 2015 reporting period.

3.18.4 Further Improvements

Bushfire management will continue to be undertaken in accordance with the Bushfire Management Plan. There were no bushfire events during the reporting period and no further improvements are currently required.

3.19 Mine Subsidence

3.19.1 Environmental Management

There was no underground or highwall mining undertaken during the reporting period. As such, no subsidence management measures were required to be implemented.

3.19.2 Environmental Performance

There was no underground or highwall mining undertaken and no subsidence occurred during the reporting period

3.19.3 Reportable Incidents

There was no occurrence of subsidence and there were therefore no reportable incidents during the reporting period.

3.19.4 Further Improvements

There was no occurrence of subsidence during the reporting period and therefore no further improvements are required.

3.20 Hydrocarbon Contamination

3.20.1 Environmental Management

All fuel and oil storage areas on site are contained within bunded areas to Australian standards or are contained within concreted workshop areas serviced by fuel and oil separation facilities.

Any material contaminated by hydrocarbons will be remediated to OEH criteria or standards or as considered appropriate.

3.20.2 Environmental Performance

There were no reportable hydrocarbon spills or other incidents causing contamination during the reporting period.

3.20.3 Reportable Incidents

There were no incidents relating to storage and handling of hydrocarbons during the 2015 reporting period.

3.20.4 Further Improvements

Should significant risks be identified or where reportable incidents occur, environmental control measures will be reviewed and additional controls implemented as required.

3.21 Methane Drainage/Ventilation

3.21.1 Environmental Management

The underground workings at Cullen Valley Mine have been closed and decommissioned. There was no underground mining conducted during the reporting period. There are no methane drainage issues and venting is not conducted at the site.

3.21.2 Environmental Performance

There are no methane drainage issues and venting is not conducted at the site.

3.21.3 Reportable Incidents

There are no methane drainage issues and venting is not conducted at the site. There were no reportable incidents relating to methane drainage or ventilation.

3.21.4 Further Improvements

There are no methane drainage issues and venting is not conducted at the site, further improvements are not currently required.

3.22 Public Safety

3.22.1 Environmental Management

Access to working areas of the open cut are controlled by locked gates. Access to the site by members of the public is via contact at the mine office where visitors or contractors can only be escorted by site personnel around the site. Warning signs have been placed on extremities of operations to ensure members of the public are aware of the presence of the open cut working.

3.22.2 Environmental Performance

No impacts or non-compliances associated with public safety occurred during the 2015 reporting period.

3.22.3 Reportable Incidents

There were no impacts or non-compliances associated with public safety and therefore no reportable incidents occurred during the reporting period.

3.22.4 Further Improvements

There were no impacts or non-compliances associated with public safety and no further improvements are currently required.

3.23 Other Issues and Risks

There were no other environmental issues or risks identified for the care and maintenance phase of the Cullen Valley Mine during the 2015 reporting period.

4 Community Relations

4.1 Environmental Complaints

Castlereagh Coal maintains a Complaints Hotline (02 6359 0600) and Complaints Register to receive and record community complaints and to effectively manage any requests for information or respond to public concerns regarding site operations.

There were two complaints received in relation to dust and noise at the Cullen Valley Mine during the 2015 reporting period. Details of these complaints are provided in Table 18.

Table 18: Details of complaints received during 2015

Date received	Received by	Complainant	Nature of complaint	Action taken
23 February 2015	Ian Follington, Coalpac	Judy Fitzgerald	Reported dust entering rear of property from the Cullen Valley Mine haul road during demobilisation of equipment.	Contacted demobilisation contractor to check if dust protocols were implemented and reinforced correct procedures for dust control. Complainant contacted to inform of actions taken.
26 May 2015	Allan Adams, EPA	Anonymous	Reported motor running at night for two weeks at Cullen Valley Mine Pit 106.	Pumping at night was ceased and will not be undertaken in future.

4.2 Community Liaison

4.2.1 Stakeholder Engagement

Castlereagh Coal commenced ownership of Cullen Valley Mine in May 2015 and the site is in care and maintenance. Castlereagh Coal is currently exploring further opportunities for community engagement processes through the development of a community consultation program for engagement with neighbouring landholders, government agencies and local communities.

The community consultation process aims to provide stakeholders and the community with appropriate opportunities to access project information and provide feedback on care and maintenance activities and future mining operations at the Cullen Valley Mine. Methods employed by Castlereagh Coal are outlined in Table 19.

Table 19: Stakeholder Engagement

Activity	Details
Community Engagement and Communications	CCC members and near neighbour consultation State and local Government briefings and meetings Employee briefings Regular community newsletters with local area distribution
Community Issues Management	Community contact line Near neighbour engagement Complaint response procedures Reporting of community complaints / concerns to the CCC and Annual Environmental Management Report (AEMR)
Community Support	Financial contributions to Cullen Bullen and wider local community groups via LCC and directly
Environmental Monitoring and Management	Environmental impact monitoring Environmental management procedures AEMR (Annual Review) reporting

4.2.2 Consultation Completed in the Reporting Period

Cullen Valley Mine is currently in care and maintenance and no mining operations occurred during the reporting period. Stakeholder consultation was therefore limited to an on-site meeting with State agencies and a meeting held with members of the Community Consultative Committee (CCC). The details of these meetings are provided in Table 20.

Table 20: Details of meetings

Meeting title	Date held	Attended by
On-site meeting with State agencies	30 July 2015	Castlereagh Coal Sedgman Department of Trade and Investment Environmental Protection Agency Forestry Corporation
CCC Meeting	25 August 2015	Castlereagh Coal Sedgman Committee chairperson Committee members
On-site meeting with Department of Planning & Environment	15 October 2015	Sedgman (Andrew O'Brien) Department of Environment & Planning (Chris Schultz)

The on-site meeting with State agencies was held to discuss future site operations and to determine agency expectations for environmental management. Agreement was reached with agencies on the ongoing management of subsurface heating, noise bund rehabilitation, rectification of soil erosion, care and maintenance operational arrangements and amendment of the care and maintenance Mining Operations Plans.

The CCC meeting was held to introduce Castlereagh Coal as the new mine owner and Sedgman as the mine operator and to reinstate the CCC following a period of administration during which little consultation has occurred. The outcomes of the CCC meeting are detailed in the meeting minutes available on the Castlereagh Coal website.

The on-site meeting with DPE was held to discuss compliance with the conditions of approvals. Agreement was reached regarding the ongoing management of subsurface heating (Cullen Valley Mine), compliance audit actions (Cullen Valley Mine), independent environmental audit (Invincible Colliery), rehabilitation works, environmental monitoring, weed spraying and the CCC committee.

4.2.3 Proposed Future Consultation

Castlereagh Coal is committed to actively participating in regular CCC meetings. Minutes of these meetings are publicly available to view on the Castlereagh Coal website: www.castlereaghcoal.com.au. The next CCC meeting is to be held in late February/early March 2016.

Castlereagh Coal is in the process of engaging a specialist consultant to design and implement a community consultation program. It is expected that this program will consist of dissemination of project information and obtaining stakeholder and community feedback through methods such as near-neighbour mail-outs, government agency briefings and community information sessions.

5 Rehabilitation

5.1 Buildings

As the site has been in care and maintenance since 2013, there were no operational activities undertaken during the current reporting period. As such, there were no renovations or removals of buildings during this time

5.2 Other Infrastructure

As the site has been in care and maintenance since 2013, there were no operational activities undertaken during the current reporting period. As such, there was no works conducted on site infrastructure during the reporting period.

5.3 Rehabilitation of Disturbed Land

5.3.1 Rehabilitation Goals and Objectives

The primary objective of site revegetation and regeneration is to create a stable final landform with acceptable post-mining land use and suitability. Disturbed areas within the mining leases will be progressively revegetated and regenerated to self-sustaining native vegetation communities.

Rehabilitation areas are to be established progressively once mining operations recommence and will be managed in accordance with the Flora and Fauna Management Plan. In the long term, rehabilitation areas are to become integrated with adjacent native vegetation communities.

Rehabilitation areas are monitored on an annual basis and will be managed until self-sustaining. Final rehabilitation areas are to achieve the rehabilitation completion criteria specified in the Cullen Valley Mine C&M MOP.

5.3.2 Success of Rehabilitation Areas

During annual biodiversity monitoring conducted in February 2015, the Compensatory Habitat Areas at Cullen Valley were assessed as having low levels of disturbance. Minor erosion and encroachment of weeds was observed. Flora diversity in these areas was comparable to the previous years of monitoring.

The target vegetation community for rehabilitation areas is grassy woodland community. Annual monitoring in rehabilitation areas detected an overabundance of *Acacia* species requiring modification of the rehabilitation seed mix. There were areas of *Acacia* dieback with resultant proliferation of groundcover species. It is expected that shorter lived *Acacia* species in these areas will be successively replaced by the longer lived *Eucalyptus* species.

Soils in these areas were found to contain large amounts of rocky material and low organic material, however, soils were considered unlikely to be a limiting factor for plant growth and rehabilitation success. Moderate to severe erosion was observed in rehabilitation areas, particularly on steeper slopes.

Surface rock and timber were observed in abundance in rehabilitation areas providing important habitat for native species. Two of the nest boxes at Cullen Valley Mine contained mammals: Gould's Long-eared Bat and Common Ringtail Possum.

Further biodiversity monitoring of rehabilitation and compensatory habitat areas was conducted during November/December 2015 however; the results of this monitoring were not available at the time of completing this report.

5.3.3 Rehabilitation Works Undertaken during the Reporting Period

No new rehabilitation areas were established during the 2015 reporting period. Full contouring and revegetation of new rehabilitation areas within Cullen Valley Mine will be undertaken once future operations recommence.

Rehabilitation works during the reporting period focused on assessment of failed vegetation in existing rehabilitation areas. Remediation of existing rehabilitation areas will be undertaken in the next reporting period in accordance with the approved Flora and Fauna Management Plan.

Rehabilitation activities undertaken during the next reporting period will include:

- Replanting/reseeding of failed rehabilitation areas in erosion washouts and subsurface heating areas and on unvegetated noise bunds (approximately 0.74 ha);
- Monitoring and reseeded (if required) of rehabilitation areas that are not yet established (approximately 15.65 ha);
- Rectification of existing erosion washouts within rehabilitation areas and repair E&S control measures (approximately 1.89 ha); and
- Repair of erosion and repair of surface cracks in subsurface heating areas (approximately 2.71 ha).

Rehabilitation objectives were monitored during the annual biodiversity monitoring conducted in February 2015 and November/December 2015 to assess the progress of rehabilitation areas. Where annual monitoring indicates that plant densities and species diversity is not in accordance with the rehabilitation success criteria, replanting and/or reseeded of failed rehabilitation areas will be undertaken and the rehabilitation seed mix will be amended as required.

Rehabilitation activities during the 2015 reporting period are shown on **Figure 7, Appendix A**.

5.4 Rehabilitation Trials and Research

Castlereagh Coal conducts monitoring and assessment of the success of rehabilitation areas within the Cullen Valley Mine site including existing nesting box trials. Annual biodiversity monitoring was conducted by Kleinfelder during February 2015 and November/December 2015.

A nesting box trial was implemented in June 2013 to provide supplementary habitat for native fauna species in rehabilitated areas. The nesting box trial consists of two plots at Cullen Valley Mine which contain six nesting boxes per plot. A further plot has been located in adjacent mature woodland as a reference site.

The type of nesting boxes selected for the trial were identified as being suitable for native species that occur in the local area. Specifically the nesting boxes were selected to provide supplementary habitat for the Squirrel glider, Gang Gang cockatoo and other parrot species, Long eared pied bat and the Kookaburra.

Annual biodiversity monitoring conducted in February 2015 found mammals were using the nest boxes at Cullen Valley Mine including Gould's Long-eared Bat and Common Ringtail Possum.

Further monitoring was conducted during November/December 2015 however; the results of this monitoring were not available at the time of completing this report.

5.5 Further Development of the Final Rehabilitation Plan

The Cullen Valley Mine Care & Maintenance Mining Operations Plan (C&M MOP) submitted to DRE on 17 December 2015 outlines the rehabilitation objectives and criteria for the Cullen Valley Mine during the care and maintenance phase. The rehabilitation plan remains unchanged from that described in the C&M MOP.

6 Activities Proposed in the Next AEMR Period

A summary of disturbed areas and rehabilitated land within the Invincible Colliery lease areas is provided in Table 21.

Table 21: Rehabilitation Summary

	Area Affected/Rehabilitated (hectares)		
	<i>To date</i>	<i>Last report</i>	<i>Next report (estimated)</i>
A. MINE LEASE AREA			
A1 Mine Lease(s) Area	1059	1059	1059
B. DISTURBED AREAS			
B1: Infrastructure Area (other disturbed areas to be rehabilitated at closure including facilities, roads)	20.6	17.9	20.6
B2: Active Mining Area (excluding items B3 - B5 below)	0	0	0
B3: Waste Emplacements (active/unshaped/in or out-of-pit)	32.5	17.6	32.5
B4: Tailings Emplacements (active/unshaped/uncapped)	0	0	0
B5: Shaped Waste Emplacement (awaits final vegetation)	4.4	18.7	4.4
ALL DISTURBED AREAS	57.5	54.2	57.5
C: REHABILITATION PROCESS			
C1: Total Rehabilitated Area (except for maintenance)	132.8	132.6	132.8
D: REHABILITATION ON SLOPES			
D1: 10 to 18 Degrees	127.2	127.2	127.2
D2: Greater than 18 Degrees	1.7	1.7	1.7
E: SURFACE OF REHABILITATED LAND			
E1: Pasture and Grasses	0	0	0
E2: Native Forest/Ecosystems	132.8	132.6	132.8
E3: Plantations and Crops	0	0	0
E4: Other (include non vegetation outcomes)	0	0	0

The discrepancies between areas reported in the last AEMR and areas reported in this AEMR are not as a result of increases in disturbed areas. There has been no further disturbance within the site since the last reporting period. The differences are as a result of improved GIS mapping prepared for this reporting period and more accurate calculation of these areas. Further, there were discrepancies in the previous AEMR (Coalpac) between unshaped waste emplacements and waste emplacement areas shown in the rehabilitation summary table and areas shown on the rehabilitation activities plan. The areas provided above are consistent with the Draft Cullen Valley Mine C&M MOP submitted to DRE on 17 December 2015.

Maintenance activities undertaken in rehabilitation areas during the 2015 reporting period and proposed in the next reporting period are outlined in Table 22.


Table 22: Maintenance Activities on Rehabilitated Land

Nature of Treatment	Area Treated (ha)		Comment/control strategies/treatment detail
	Report Period	Next Period	
Additional erosion control works	0	1.89	Repair and reconstruction of erosion control devices
Re-covering	0	0	NA
Soil treatment	0	0	NA

Area Treated (ha)			
<i>Nature of Treatment</i>	<i>Report Period</i>	<i>Next Period</i>	<i>Comment/control strategies/treatment detail</i>
Treatment/management	0	2.71	Repair of erosion control devices and surface cracks in subsurface heating areas
Reseeding/replanting	0	0.74	Replanting/reseeding in existing rehabilitation areas
	0	15.65	Monitoring and reseeding (if required) in existing rehabilitation areas and subsurface heating areas
Adversely affected by weeds	29.2	28 (estimate only – as this will depend on the extent of weed infestations observed at the time)	Weed spraying program
Feral animal control	0	0	NA

Appendix A

Site Plans




Cullen Valley Mine
Annual Environmental Monitoring Report 2015
Date: 21/01/2016


FIGURE 2
PROJECT LOCATION

- Legend**
- Mine Disturbance Area
 - National Park
 - State Forest
 - Main Roads
 - Major Rivers and Creeks
 - Railway






- Legend**
- | | | |
|---------------------------|----------------------------|------------------|
| Major Rivers and Creeks | Water Management Structure | Ownership |
| Buildings, Dwellings | Infrastructure | Crown Land |
| Building | Railway | Mine Owned Land |
| Private Freehold Dwelling | Main Roads | Privately Owned |
| Mine Owned Dwelling | Cadastral Boundaries | State Forest |
| Mining Tenements | | |
| Mine Disturbance Area | | |
| Water Pipeline | | |




- Legend**
- | | |
|----------------------------|--------------------------|
| Major Rivers and Creeks | Infrastructure Areas |
| Mine Disturbance Area | Haul Roads, other roads |
| Mining Tenements | Sub Surface Heating Area |
| Conveyor | External Dams |
| Water Pipeline | Mining Activities |
| Railway | Active Mining: Pre 2008 |
| Main Roads | Active Mining: 2008-2009 |
| Water Management Structure | Active Mining: 2013 |
| | 2014 - 2015 - No Mining |




Cullen Valley Mine
Annual Environmental Monitoring Report 2015
Date: 21/01/2016

**FIGURE 5
ENVIRONMENTAL MONITORING
LOCATIONS**

- | | | |
|---|---|--|
| <ul style="list-style-type: none"> Major Rivers and Creeks Mining Tenements Mine Disturbance Area Conservation & Offset Areas Under Species Management Plan Railway Conveyor Water Pipeline Main Roads | <ul style="list-style-type: none"> Water Management Structure Infrastructure State Forest Aboriginal Heritage Site Non-indigenous heritage site Sample Sites Blast Monitor Compensatory Habitat | <ul style="list-style-type: none"> Depositional Dust Groundwater Monitoring Bore Meteorological Station Noise Monitor PM10 Monitor Surface Water Monitoring Location |
|---|---|--|



- Legend**
- Major Rivers and Creeks
 - Mining Tenements
 - Mine Disturbance Area
 - Conveyor
 - Water Pipeline
 - Water Management Structure
 - Infrastructure
 - Railway
 - Main Roads
- Subsurface Heating Area Monitoring Locations**
- Lithgow Seam Temperature Probe
 - Temperature Probe
 - Thermal Image Monitoring Location
 - Water Monitoring Bore




Appendix B

Wind Roses

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/01/2015 - 00:00
End Date: 11/12/2015 - 07:00

COMPANY NAME:

MODELER:

CALM WINDS:

38.00%

TOTAL COUNT:

8263 hrs.

AVG. WIND SPEED:

0.92 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/01/2015 - 00:00
End Date: 31/01/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

34.63%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

0.90 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/02/2015 - 00:00
End Date: 28/02/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

32.84%

TOTAL COUNT:

672 hrs.

AVG. WIND SPEED:

0.83 m/s

DATE:

22/01/2016



PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)WIND SPEED
(m/s)

Calms: 39.60%

COMMENTS:

DATA PERIOD:

Start Date: 1/03/2015 - 00:00
End Date: 31/03/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

39.60%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

0.88 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/04/2015 - 00:00
End Date: 30/04/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

36.06%

TOTAL COUNT:

720 hrs.

AVG. WIND SPEED:

0.89 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/05/2015 - 00:00
End Date: 31/05/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

34.36%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

1.10 m/s

DATE:

22/01/2016



PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)WIND SPEED
(m/s)

Calms: 52.84%

COMMENTS:

DATA PERIOD:

Start Date: 1/06/2015 - 00:00
End Date: 30/06/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

52.84%

TOTAL COUNT:

720 hrs.

AVG. WIND SPEED:

0.61 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/07/2015 - 00:00
End Date: 31/07/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

40.27%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

0.97 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

**Wind Speed
Direction (blowing from)**

COMMENTS:

DATA PERIOD:

Start Date: 1/08/2015 - 00:00
End Date: 31/08/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

35.84%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

1.06 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

**Wind Speed
Direction (blowing from)**

COMMENTS:

DATA PERIOD:

**Start Date: 1/09/2015 - 00:00
End Date: 30/09/2015 - 23:00**

COMPANY NAME:

MODELER:

CALM WINDS:

43.13%

TOTAL COUNT:

720 hrs.

AVG. WIND SPEED:

0.88 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/10/2015 - 00:00
End Date: 31/10/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

39.19%

TOTAL COUNT:

744 hrs.

AVG. WIND SPEED:

0.90 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

Wind Speed
Direction (blowing from)

COMMENTS:

DATA PERIOD:

Start Date: 1/11/2015 - 00:00
End Date: 30/11/2015 - 23:00

COMPANY NAME:

MODELER:

CALM WINDS:

31.35%

TOTAL COUNT:

720 hrs.

AVG. WIND SPEED:

1.05 m/s

DATE:

22/01/2016


PROJECT NO.:

A399-D01

WIND ROSE PLOT:

CULLEN VALLEY MINE - LITH001

DISPLAY:

**Wind Speed
Direction (blowing from)**

COMMENTS:

DATA PERIOD:

**Start Date: 1/12/2015 - 00:00
End Date: 11/12/2015 - 07:00**

COMPANY NAME:

MODELER:

CALM WINDS:

29.44%

TOTAL COUNT:

247 hrs.

AVG. WIND SPEED:

1.13 m/s

DATE:

22/01/2016

PROJECT NO.:

A399-D01